


Product Safety Recall



Production Code

Lamaze Chill Teether™ Single Pack

Product Code Y5288L

Only teethers with production code K1920ALP01 or E1920ALP01 are included in this recall. Sold in NZ between 1st March 2021 to present

Defect: The recall is due to microbial contamination. The liquid filling in production code K1920ALP01 is contaminated with the bacteria *Sphingomonas* sp and the liquid filling in production code E1920ALP01 is contaminated with the bacteria *Staphylococcus epidermidis*

Hazard: Product contaminated with *Sphingomonas* sp or *Staphylococcus epidermidis* may cause infection or illness in children with weakened immune system if teether is punctured and the liquid filling is ingested

What to do: Consumers should immediately stop using the product and keep out of reach of children.

The production code can be found directly on the back of the packaging and on the product itself. Only teethers with production code K1920ALP01 and E1920ALP01 are included in this recall

Contact details: Please return the item to :

Baby First NZ, 25 Nga Mahi Road, Sockburn, Christchurch 8042

Baby First will provide a replacement Lamaze item to all affected consumers. Do not return the item to store

New Zealand Importer/Distributor

Baby First New Zealand

25 Nga Mahi Road, Sockburn, Christchurch :
New Zealand

Email: customerservice@babyfirst.co.nz

Phone: +64 (3) 338 7613

See www.recalls.govt.nz for
other New Zealand consumer product recalls