## **CUSTOMER NOTICE**FROM DOREL NEW ZEALAND

Dear valued customer,

We are making contact regarding a voluntary recall reported in the USA of some Maxi Cosi capsule bases.

In New Zealand, there are two models – Maxi Cosi Coral XP (IC313FNB) and Maxi Cosi Mico XP Max (IC337FNA).

When the car seat is installed into the vehicle with the base secured using the lower anchors/latch system this may not adequately protect the child in an event of a crash

Dorel Juvenile USA have recommended the following;

For continued use of your capsule and base, we ask that the base be installed using only the vehicle belt restraint, or with shell only (without base) installation using the vehicle belt restraint.

## Remedy:

We are currently manufacturing new bases for the replacement.

A free replacement base will be sent directly to registered owners as soon

as they become available. To become a registered owner, go to www.maxi-cosi.co.nz/service/warranty-registration.

If you have any questions regarding this, please contact Dorel New Zealand on 0800 628 000, Monday through Friday from 8.30am to 5.00pm, or email us at customerservice@dorel.co.nz

















