


# Product Safety Recall



Serial numbers starting with the following 4 digits:

- a. **TM5A**YYWWXXXXXX,
- b. **TM5B**YYWWXXXXXX,
- c. **TM5C**YYWWXXXXXX



## Philips Avent Digital Video Baby Monitor

*Baby Monitor – SCD620/79*

*Retailers selling baby products and produced between January 2016 and March 2018.*

**Defect:** Battery in the parent unit overheating while plugged into the electrical connection.

**Hazard:** In very rare cases, this poses a potential fire hazard.

**What to do:** Owners with an affected baby monitor should stop using the baby monitor and contact the Philips Consumer Care team for a refund or replacement. If your product is not affected, you can continue to safely use your baby monitor.

**Contact details:** Please visit [www.philips.com/babymonitor-recall](http://www.philips.com/babymonitor-recall) or call, with your baby monitor at hand to check if your product is affected.

**Phone:** 0800 658 224 [Option 2]

**Online:** [www.philips.co.nz/support](http://www.philips.co.nz/support)

**New Zealand Importer / Distributor** Endeavour Consumer Health, Ebos Group Ltd,  
14 – 18 Lovell Court Rosedale 0632, Auckland New Zealand, 0800 658 224 [Option 2]